



The brands of the BPW Group:



NEWS Aftermarket



73711706e

AM02 / 2017

Amendment of repair kits

09.801.06.26.0 -> 09.801.06.26.1


09.801.06.27.0 -> 09.801.06.27.1

09.801.07.04.0 -> 09.801.07.04.1

To avoid incorrect assembling the a.m. new repair kits will not contain the thrust washer 03.320.64.01.0.



In 2014, the combination of axle nut 05.266.47.06.0 with thrust washer 03.320.64.01.0 has been replaced by the combination of axle nut 05.266.47.11.0 with thrust washer 03.320.65.05.0.



A different combination of axle nut and thrust washer as explained above is not permitted. Incorrect assembling may cause further damages!

