




New repair kits for the ECO Plus 3

For the BPW ECO Plus 3 axle generation launched in mid-May, the following repair kits have been developed.


09.801.08.36.0

BPW Complete Hub ECO Plus 3 B-Hub




09.801.08.40.0

Roller bearing repair kit with axle nut and hub cap



09.801.08.41.0

Roller bearing repair kit without axle nut and hub cap




05.212.25.98.0 Hub cap incl. O-ring

05.212.25.99.0 Hub cap, chromium-plated*, incl. O-ring

*(Not corrosion-resistant acc. to DIN 50021)



16.038.22953 Magnet wheel assembly tool



Please note!

With the conversion to ECO Plus 3, the following brake discs will be replaced with new versions:

Overview of brake discs

| | old | new |
|----------------------------|--------------------------|--------------------------|
| TSB 3709 | 03.088.34.14.0 / .7 / .8 | 03.088.34.21.0 / .7 / .8 |
| | 03.088.34.17.0 / .7 / .8 | 03.088.34.22.0 / .7 / .8 |
| TSB 4309 / TSB 4312 | 03.088.35.05.0 / .7 / .8 | 03.088.35.12.0 / .7 / .8 |

(further details in NEWS 73161508)