











## NEWSAftermarket @



75022201e

AM04 / 2022


## Conversion of brake shoes for 10 - 12 t low loader trailer axles

Brake shoe 05.091.14.77.1 is being replaced by brake shoe 05.005.79.34.1 as part of a product optimisation process for 10 - 12 t low loader trailer axles with brake SN 3020.


As part of this optimisation, the brake roller bolt will now be welded to the brake shoe bridging plate to increase strength for axle loads ≥ 10 t.

Following the introduction of new brake shoe 05.005.79.34.1, a new repair kit (09.801.09.35.0) will now be available for axle loads  $\geq$  10 t.

The old version (05.091.14.77.1) will still be available for 9 t low loader trailer axles with brake SN 3020.



Brake shoe: 05.091.14.77.1 (still valid for 9 t axles with SN 3020)



Brake shoe: 05.005.79.34.1 Repair kit: 09.801.09.35.0



